

Ni基合金におけるγ'相の析出形態形成機構の解明

[キーワード: Ni基超合金, 析出形態, γ'相] 助教 久澤大夢



内容:Ni基合金におけるγ'析出相の, 形や分布と言った析出 形態の形成機構を明らかにするための研究を行っています.

Ni基超合金は火力発電所やジェットエンジンを筆頭とした 過酷な環境で使用される構造用材料です。高温で使用され るために、その組織は図のように使用中に刻一刻と変化し、 その析出物であるγ'相は立方体に近い特異な形状を示すこ とが有名です。その形成機構は理論的な考察が進んでいる ものの、商用合金の組成が複雑であることもあり評価が難し いため、実験的な検証が進んでいません。


- ① そこで、基本的な合金系を用いるなど、その評価のための実験条件を吟味し、析出形態に影響を及ぼす要素を抽出するための実験を行っています。析出形態の形成機構の包括的な理解を目指します。
- ② 析出形態の評価は難しいため、画像処理を用いた「析出 形態の定量化方法」を開発しています。これによって析 出形態を客観的に表現したり、見ただけではわからな かった新しい知見を発見することができます。 Ni基合金は最も単純な2相合金ですのでモデル合金とし ても最適であり、他の系における組織の定量化への応用 も目指しています。

分野:材料組織制御工学

専門:材料科学


E-mail: hisazawa.hiromu@tokushima-u.ac.jp

Tel. 088-656-7361 Fax: 088-656-9082





Development of Cuboidal γ' Phase in Ni-based alloys Assistant Professor Hiromu Hisazawa



Content: We are tying to unclear the mechanism of γ' morphology (shape, distribution and other characteristics of γ' precipitates) in Ni-based alloys.

Ni-based alloys are famous as a structural material at high temperature such as power generators and jet engines, whose microstructure are dramatically changing in service as shown in left figures. γ' precipitates make the alloy strong and its morphologies should affect the performance. We are trying to understand and control them through following approaches.

- ① Simple alloy system and special experiment conditions were carefully selected to extract the key factor of γ' morphologies. It is just for understanding mechanism of γ' morphologies directly.
- $\ 2$ The imaging process to evaluate the γ' morphologies is being developed due to the difficulties of explanation and discovery of them. The Ni-based alloys are ones of the most simple 2 phase alloy, which is desirable as a model case of "computing microstructure quality management".

Keywords: Ni-based alloy, precipitation morphology, gamma prime phase

E-mail: hisazawa.hiromu@tokushima-u.ac.jp

Tel.: +81-88-656-7361 Fax: +81-88-6569082

